



BOILER FAILURE AFTER REFURBISHMENT REQUIRES FAST TEMPORARY REPLACEMENT



The Challenge

Following the extensive refurbishment of a leisure centre the building's on-site boiler failed and a quick replacement was needed fast.

ICS Cool Energy

"Our 1.3MW boiler is energy efficient providing excellent economy and is housed in a lockable ISO container which is so important on sites where the public are present."

WE MAKE IT WORK

The Solution

After an on-site assessment a 1,3MW boiler was delivered and installed within 24 hours. The heating only boiler provided hot water to a plate heat exchanger. Its low noise design proved to be ideal as local housing backed onto the swimming pool's site.



The Result

The centre was soon after able to reopen and provide a popular service to the local community.



I find ICS an absolute pleasure to deal with, they are always available to help when needed and will pull out the stops to make sure equipment is on site when needed no matter how short the notice.



5 Star review on Trustpilot.com



TRUSTPILOT

Date code: 11/17

Our International offices:

Ireland: +353 (0)46 92 52934


Netherlands: +31 (0)88 258 258 0

Austria: 00800 0116 0117

Germany: +49 (0)7046 88087 0

Switzerland: +41 (0)55 415 91 09

France: +33 1 60 66 80 83

 UK HIRE: 0800 840 4210

 hire@icscoolenergy.com